## **ABSTRACT**

A driver circuit is provided for a stepper motor which utilizes a processor that outputs a PWM signal. The driver circuit includes an H-bridge circuit having first and second inputs, and a switching circuit having an input and an output. The first H-bridge input and the switching input connect to the PWM signal output from the processor, and the switching output connects to the second H-bridge input. The switching circuit performs an inversion of a duty cycle of the PWM signal when the PWM signal is present, and a non-inversion of the duty cycle when the PWM signal is not present.

K:\0515\67242\Application.doc

a grand to be a significant